

GARMIN

CRADLE SET O

P11186

MAY 2020

ASSEMBLY DIAGRAM


Tools Required




SECURITY TORX X20

Parts

(A) x1



(B) x1




(C) x2
M4 X 6




(D) x2




1



2



3



4

