

Garmin

R10 KIT Basic Display

P11127

July 2021

ASSEMBLY DIAGRAM

Tools Required - Supplied

Torx X10


Torx X20

Parts

Not Supplied

(B) x1

(A) x1



Parts

R10 Cradles Kit

(D) x1

(E) x1


(C) x1

(H) x1

(F) x1

(G) x1

(O) x1



Fixings

(I) x4 M4x6


(J) x2 M4x10

(K) x2


(L) x2

(M) x2

(N) x2 12 OD METAL



1




(B) x1

(A) x1

(M) x2

2




(C) x1


FRONT

BACK


3



4




5



(E)

(F)

6




Torx X20


(J)

(G)


7




8




9




10



11




12




13


S2 CRADLE



14



15



16

