

GARMIN

CRADLE M3

P11186

MAR 2023

ASSEMBLY DIAGRAM


Tools Required - Supplied




SECURITY TORX X20

Parts

(A) x1



(B) x1



(C) x1



(D) x2
M4x8




(E) x2



1

(A) x1



2


(C) x1

(E) x2


LOOSE

(D) x2
M4x8

(B) x1



3



4

