


GARMIN

CRADLE SET O3

P11186 23/01/2025


ASSEMBLY GUIDE

Tools Required (not supplied)



SECURITY TORX X20
SECURITY TORX X30

Parts



(A) x1



(B) x1



(C) x2 M4 SPRING
WASHER



(D) x2 M4 X 6MM
SECURITY TORX
BUTTON SCREW -
X20 DRIVE




(E) x1 M6X8MM
SECURITY TORX
SCREW BUTTON
HEAD X30
DRIVE




(F) x2 M4X12MM CSK
SECURITY TORX
SCREW X20
WITH PIN


1




2



3



4



FIXING MUST BE
TIGHT

5



GARMIN®