


GARMIN

CRADLE X50

P11186 09/12/2024 Rev A

ASSEMBLY GUIDE


Tools Required




SECURITY TORX X20

Parts

(A) x1



(B) x1



(C) x2




M4 X 6MM TORX BUTTON HEAD

(D) x2




(E) x1




1

(E) x1




2


(A) x1



3



4




5

(B) x1


(C) x2

(D) x2



SECURITY TORX X20

6



RECYCLING

