


GARMIN

CRADLE E2

P 11186 | SEPT 2019

ASSEMBLY DIAGRAM


Tools Required




SECURITY TORX X20

Parts


(A) x1



(B) x2




(C) x2




(D) x2
M4x8



1



2



3

