

GARMIN

CRADLE K2

P 11186


MAY 2020

ASSEMBLY DIAGRAM

Tools Required



Parts




(A) x1




(B) x2
M4x16

1



2



3

