

GARMIN

CRADLE K3

P 11186 | OCT 2021


ASSEMBLY DIAGRAM

Tools Required



SECURITY TORX X20

Parts




(A) X1




(B) X1

M4X6MM

1



2



3

