

GARMIN


CRADLE M2

P11186

JULY 2022

ASSEMBLY DIAGRAM


Tools Required




SECURITY TORX X20

Parts


(A) x1




(B) x1



(C) x1



(D) x1




(E) x2
M4x8




(F) x2




1



2



3



4

