

GARMIN

CRADLE P3

P 11186 | OCT 2021

ASSEMBLY DIAGRAM

Tools Required



SECURITY TORX X20

Parts




(A) X1



(B) X1




(C) X2
M4X6MM




(D) X2

1



2



3

