

GARMIN

CRADLE R10

P 11186

OCT 2021


ASSEMBLY DIAGRAM

Tools Required




SECURITY TORX X20


Parts



(A) x1



(B) x1




(C) x1




(C) x2
M4X6MM

1



(A) x1


2



(B) x1

(C) x1

3



(C) x2
M4X6MM

4

