

GAMRIN


CRADLE SET R1

P11186

MAY 2020

ASSEMBLY DIAGRAM


Tools Required




SECURITY TORX X20

Parts

(A) x1



(B) x2




(C) x2
M4x6




(D) x2



1



2



3

