

GARMIN

CRADLE S1

P11186

15.05.2020


ASSEMBLY DIAGRAM

Tools Required




Parts

(A) x1



(B) x1




(C) x2
M4x10




(D) x2



1



2



3

