

GARMIN

CRADLE W1

P 11186

OCT 2021


ASSEMBLY DIAGRAM

Tools Required




SECURITY TORX X20

Parts



(A) X1




(B) X1




(C) X2
M4X6MM

1



2



3

