



ASSEMBLY DIAGRAM


Tools Required - Supplied




Parts



(A) x1




(B) x2



(C) x1

(D) x8
M6x10(E) x2
M4x6

(F) x1




(G) x1




(H) x1


1




2



3



4



5

