

GARMIN


CRADLE M1

P 11186

SEPT 2019

ASSEMBLY DIAGRAM


Tools Required




SECURITY TORX X20

Parts


(A) x1



(B) x2




(C) x2



(D) x2
M4x6



1



2

