

GARMIN


CRADLE Q1

P11186

MAY 2020


ASSEMBLY DIAGRAM

Tools Required



Parts


(A) x1




(B) x8



1



2



3

