

GARMIN

# CRADLE S2

P 11186

OCT 2021

## ASSEMBLY DIAGRAM

### Tools Required




SECURITY TORX X20

### Parts



Ⓐ X1




Ⓑ X1




Ⓒ X2  
M4X6MM

1



2



3

