

GARMIN

CRADLE SET U

P11186

SEPT 2020


ASSEMBLY DIAGRAM

Tools Required




SECURITY TORX X20

Parts




(A) x1



(B) x1




(D) x2
M4x8




(C) x2
M4x12

1



2



3

